

G5 Flush Mount Bracket. Rev 2

*Rivet holes may rotate 90 degrees if there is an obstruction
but the G5 cut must remain the same.

